

Improvements of the Tungsten Guard Limiter of 4.6GHz Lower Hybrid Wave Antenna of the EAST and its Service Status under Operations


by

L. Yin^{1*}

D.M. Yao¹, R. Ding¹, C.L. Liu², M. Wang¹, P.F. Zi¹, M.H. Li¹, L. Cao¹, L. Li¹, L. Han¹, T.J. Xu¹, Z.L. Wang¹


¹Institute of Plasma Physics, Chinese Academy of Sciences

*E-mail: lei.yin@ipp.ac.cn



- 1 Review of the GL with Graphite tiles**
- 2 Review of the obsolete Tunsgten Guide Limiter
- 3 Improvement of the Tunsgten Guide Limiter
- 4 Service Status under the EAST Operations
- 5 Summary




Brief Introduction of the EAST



- **Feature:**
 1. non-circular cross-section
 2. fully superconducting magnets
 3. fully actively water cooled plasma facing components
- **Mission:**

conducting ITER-like steady-state advanced plasma research

Overview of the EAST LHCD and GL




Main Parameter of 4.6GHz LHCD

- Maximum 6MW
- Long-pulse (>1000 s)
- FAM launcher with **actively water cooling**

Design Requirements of the GL


1. GL 3mm higher than the LHWA grill in mid-plane, located at R2356mm .
2. GL should be 3mm higher than the LHWA grill in the poloidal cross section, R757mm .



- [1] C.L. Liu et al. IEEE T. PLASMA SCI. 50 (2022) 990
 [2] C.L. Liu et al. Fusion Eng. Des. 2017
 [3] L.L. Zhang et al. Fusion Eng. Des. 2018



Review of the Obsolete Designs

High Heat Flux Component for the GL






High Heat Flux Component available in EAST

Graphite Tiles






steady state :
2MW/m²

Monoblock



steady state :
10MW/m²



Flat-tile



steady state :
20MW/m²


Obsolete GL consisting of Graphite tiles

Overall Limiter structure





- Graphite tiles coated with SiC, CuCrZr heat sink with stainless support frame.
- **low thermal conduction** due to poor contact
- Design target ~ **2.0 MW/m²**.

C.L. Liu et al. Fusion Eng. Des. 2017



2014



2015




M. Wang et al. Nucl. Eng. Technol. 2022




Assumption:

- ✧ A layer of fast electrons exist adjacent to the grill
- ✧ Heat load of fast electrons goes approximately toroidally

Obsolete GL consisting of Graphite tiles





No Melting Grooves



Cracks

2016

C.L. Liu et al. Fusion Eng. Des. 2017



2017


L.L. Zhang et al. Fusion Eng. Des. 2018

- 1 Review of the GL with Graphite tiles
- 2 Review of the obsolete Tungsten Guide Limiter**
- 3 Improvement of the Tungsten Guide Limiter
- 4 Service Status under the EAST Operations
- 5 Summary


Obsolete Tungsten GL

设计及工艺


Contour of the Monoblock



Contour of the Endbox




Overall Structure



L.L. Zhang et al. Fusion Eng. Des. 2018

Service History of the Obsolete Tungsten GL



2017.11 First installation




1. Melt on the end boxes
2. Melt on the inner corners of the monoblocks

First Modication of the Obsolete Tungsten GL

Reason for the Ablition of the End Box

Bend



previous graphite tils GL



No Bend






new Tungsten GL



New Design



Service History of the Obsolete Tungsten GL





2020.8-2021.4 upgrade



After 2021 Spring Campaign

Service History of the Obsolete Tungsten GL

After 2021 Autumn Campaign





After 2022 Spring Campaign



Modification and Rectification

Cause Analysis for Damage:

1. Melting on the top



Possible Reason:



- ① Incident heat flux on the corner
- ② Low heat exhaust ability of the top
- ③ Potential assemble misalignment

Suggestion:

- ① Top of the GL should be on one monoblock

Cause Analysis for Damage:

2. Melting on the Inner Fillet



Possible Reason:

- ① Incident heat flux on the Fillet
- ② Fast Electron Layer close to the grill
- ③ Potential assemble misalignment

Suggestion:


- ① Set the inner corner below the grill(considering misalignment)

Cause Analysis for Damage:

3. Melting on the End Box

Upper End Box

Lower End Box



Possible Reason:

- ① Poor local heat exhaust ability
- ② Closet location to the plasma

Suggestion:

- ① Elongate the monoblock components




- 1 Review of the GL with Graphite tiles
- 2 Review of the obsolete Tunsgten Guide Limiter
- 3 Improvement of the Tunsgten Guide Limiter**
- 4 Service Status under the EAST Operations
- 5 Summary


Modification and Rectification

Modification:

2. Design of the End box




3. Overall Structure



Modificaiton and Rectification

Processing procedure



Monoblock

CuCrZr

HIP:600°C 100MPa



Monoblock component: welded by HIP

Supplied by Advanced Technology & Materials Co., Ltd





Assemble Requirement

Profile tolerance: $\pm 0.5\text{mm}$




Misalignment: 0.5mm

by Hefei Keye manufacturing Co., Ltd



componets



post 1



post 2




installation



implemented by Hefei Juneng Electron Physics High-tech Development Co., Ltd


Service under the EAST experimental operation



	Line 1	Line 2	Line 3
Design Value	23	48	77
Measured Value	24	56	83

- No visible Damage found on the surface of the GL
- A dividing line found between the shadowed and unshadowed area

2023.03-2023.08 Campaign



copper leakage location




#129160

hotspot

#129160

hotspot



#Shot129160 :


I_p 310KA, 13.2s, ne~4.5
LH2~2.3MW
EC~2MW
IC~2.5MW
NBI_1L~50kV
NBI_1R~55kV
NBI_2R~55kV

Lasting 3.8s

Over CHF?

Estimation CHF

Original




coolant pressure: 0.6MPa
coolant temperature: 27°C

Using Tong-75

Flow speed (m/s)	Coolant temperature (°C)	CHF (MW/m ²)
5	27	~29.8
6	27	~32.2
7	27	~34.4
8	27	~36.5
9	27	~38.3
10	27	~40.1

Improved



coolant pressure: 2MPa
coolant temperature: 27°C
coolant speed : 7.4m/s

Using Tong-75


CHF (MW/m ²)	
Max. allowable heat flux (MW/m ²)	41
Max. temperature (Wu) /°C	2933
Max. temperature (CuCrZr Pipe) /°C	954
melting point (CuCrZr) /°C	1080

critical warning temperature

by L. Han, ASSIP

mitigate

Original




PHF(parallel heat flux)

$$\text{CHF} \geq 34.4 \text{ MW/m}^2$$

$$\text{CHF} = \text{PHF} * \sin 22^\circ$$

➡ $\text{PHF} = 91.7 \text{ MW/m}^2$

Improved



VHF(vertical heat flux)

$$\text{VHF} = \text{PHF} * \sin 22^\circ$$



$$\text{PHF} = 91.7 \text{ MW/m}^2$$

➡ $\text{VHF} = 29.8 \text{ MW/m}^2$

Decreased by 13.3%

- **In order to mitigate the cracks, melting or ablations on the GL of the 4.6GHz LH antenna, efforts have been made:**
 - **Upgrading the guard limiters from graphite tiles to tungsten monoblock limiter**
 - **Ablation on the inner corner eliminated, by moving the corner behind antenna**
 - **Ablation on the top of the GL eliminated, by move the top of GL to one monoblock**
 - **Ablation on the bend of the GL mitigated, by moving back of the bend from the plasma.**
- **The leakage in the last shot#129160:**
 - **High possibly caused by the CHF event, according to observation**

- **To Solve the CHF events**
 - To increasing CHF of the GL as much as possible.
 - To ease vertical heat flux on the GL.
 - To get reliable heat flux data .
- **Design of the new GL of 4.6GHz PAM LHWA in port B**
 - End box with low heat exhaust ability locating near the mid-plane where heat flux is extremely high



Thank You

*The authors acknowledge the financial support from the National
MCF Energy R&D Program (2018YFE0312300)*